

承湘科技股份有限公司

Smart Vision System

Abnormal wafer production inspection

Image Inspection

Wafer & Arm shift

Unexplained deviation of wafers or arms during transfer in the semiconductor factory Causes the subsequent process to be divorced, but the deviation cannot be quantified and warned We provide reconstruction services such as image recognition, and assist in visual inspection mechanisms.









